
From: Ann Rodriquez <[REDACTED]>
Sent: Wednesday, August 2, 2017 7:22 PM
To: jeffrey E.; Rich Kahn; Daphne Wallace
Subject: LSJ Main Generators: Not good
Attachments: IMG_9480.JPG; Untitled attachment 00208.txt; IMG_9481.JPG; Untitled attachment 00211.txt; IMG_9485.JPG; Untitled attachment 00214.txt; IMG_9491.JPG; Untitled attachment 00217.txt; IMG_9496.JPG; Untitled attachment 00220.txt; IMG_9504.JPG; Untitled attachment 00223.txt; image1.JPG; Untitled attachment 00226.txt; image2.JPG; Untitled attachment 00229.txt; image4.JPG; Untitled attachment 00232.txt; image3.PNG; Untitled attachment 00235.txt

Hey Bossman,

Danny just told me that the 1st generator sprung a coolant leak (first 6 photos) and the 2nd Generator belt has burst (photos 7&8) 2nd Generator is down= LSJ is currently running on 1 generator at the moment.

He asked if Tap can fix it for him. Tap said it's pretty bad but he can fix it if we get all the parts. I told Danny V. to call Plan B Generator company to come out tomorrow morning or asap.

The Generator is running because we had another power outage this morning and it blew out the repeater for the R/O again. (last 2 photos)