

---

**From:** jeffrey E. <jeevacation@gmail.com>  
**Sent:** Tuesday, May 23, 2017 4:32 PM  
**To:** Brice Gordon  
**Subject:** Re: ZM Mercedes S500

Ok

On Tue, May 23, 2017 at 12:23 PM=Brice Gordon <[REDACTED]> <=a>> wrote:  
<mailto:[REDACTED]>

Jeffrey

attached Video and Repair estimate for your reference

During the final =nspection of the Mercedes S 500, the Technician discovered found oil and w=ter contamination in the Transmission control unit.This is due to failed E=ectronic connector at the Transmission

The cost to repair will be an additional \$1447.879

Total Cost of repairs, as of date, including=the above, less tax \$8297.87

Do you wish to proceed with repair?

regards

Brice Gordon  
Stanley, NM

Ph: [REDACTED]

--

=C2 please note

The information contained in this communication =s confidential, may be attorney-client privileged, may constitute in=ide information, and is intended only for the use of the addressee. It =s the property of JEE Unauthorized use, disclosure or copying of thi= communication or any part thereof is strictly prohibited and may be=unlawful. If you have received this communication in error, please noti=y us immediately by return e-mail or by e-mail to jeevacation@gmail.com <mailto:jeevacation@gmail.com> , and des=roy this communication and all copies thereof, including all attachment=. copyright -all rights reserved

--94eb2c0433e27a97bb05503386b1-- conversation-id 43188 date-last-viewed 0 date-received 1495557113 flags 8590195713 gmail-label-ids 7 6 remote-id 716239