
From: jeffrey E. <jeevacation@gmail.com>
Sent: Tuesday, April 25, 2017 10:50 AM
To: Eric Roth; Richard Kahn; Ivjet
Subject: Re: G550 sn 5173 Proposal

cabin seats are NOT LEATHER not sure why there are so many errors

On Mon, Apr 24, 2017 at 7:20 PM, [REDACTED] wrote:

Jeffrey,

Attached is our detailed proposal to refurbish your G550. We have spent considerable time creating what we believe to be inclusive of almost all items that we have discussed over the last few months.

Kindly read through this specification to ensure that we have covered all "known / defined" items requested.

Please note this proposal does not include:

- * *A0 All shades controlled at CEO chair (This feature was originally programmed in the two (2) Pronto remotes which were originally outfitted)
- * *A0 New monitor to replace existing 2" monitor in fwd bulkhead
- * *A0 Chinchilla / sheepskin slip cover for the two (2) divans

As always, please do not hesitate to call me with any questions you may have.

Thank you.

Best Regards,

Eric

ERIC H. ROTH<=> | PRESIDENT

2221 Smithtown Avenue, Long Island MacArthur Airport, Ronkonkoma, New York 11779<=>

--
=A0 please note

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of JEE. Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to jeevacation@gmail.com, and destroy this communication and all copies thereof, including all attachments. copyright -all rights reserved