
From: Hugo Hodge <[REDACTED]>
Sent: Monday, April 3, 2017 5:34 PM
To: jeffrey E.
Subject: Re: thanks hugo,

The panels, inverter setup,=generator controls in the back, wiring, smell of gasoline, etc.
=div>

The option with a cable from LSJ to GSJ as the primary f=ed is unreliable because it's one radial feed, meaning it comes from just o=e direction and one route. Any damage to the utility feeder, pad, switch, o=cable and both LSJ and GSJ are out of power until repairs are completed. W=ile this is currently the case you would have more exposure with two system=. This includes damage to the switch caused by a fault on either of your tw=islands.

On Apr 3, 2017, at 1:22 PM, jeffrey E. <jeevacation@gmail.com> wrote:

<=div>

what sepcifically neede= cleaning panel? batteries? =, why is the cable from lsh to GSJ unreliable , any more than current=y

--

&nb=p; please note

The information contained in this communicatio= is confidential, may be attorney-client privileged, may constitute i=side information, and is intended only for the use of the addressee. It i= the property of

JEE

Unauthorized use, disclosure or copying of this<=r>communication or any part thereof is strictly prohibited and may be un=awful. If you have received this communication in error, please notify u= immediately by return e-mail or by e-mail to jeevacation@gmail.com <mailto:jeevacat=on@gmail.com> , and destroy t=is communication and all copies thereof, including all attachments. copy=ight -all rights reserved

=