
From: Larry Visoski [REDACTED]
Sent: Wednesday, May 23, 2018 8:45 PM
To: Je vacation
Subject: G650 fly/by/wire

Jeffrey

While in Paris this past trip, I spoke to the Gulfstream Fast Team mechanics, I asked him what was the most common issue when called out to the G650 =99s Gulfstream FastTeam support informs 80% of their call outs are for Fly-by-wire software issues, typically the 650 was Gulfstream's first attempt at fly/by/wire system, it is the test bed for the Joy Stick system in the G=00/G600

Thought that was interesting

Thx
Larry

Sent from my iPhone=<?xml version=.0" encoding=TF-8"?> <!DOCTYPE plist PUBLIC "-//Apple//DTD PLIST 1.0//EN" "http://www.apple.com/DTDs/PropertyList-1.0.dtd">
<plist version=.0">
<dict>
 <key>conversation-id</key>
 <integer>5727</integer>
 <key>date-last-viewed</key>
 <integer>0</integer>
 <key>date-received</key>
 <integer>1527108305</integer>
 <key>flags</key>
 <integer>8590195713</integer>
 <key>gmail-label-ids</key>
 <array>
 <integer>2</integer>
 </array>
 <key>remote-id</key>
 <string>823402</string>
</dict>
</plist>