

---

**From:** Ann Rodriguez - [REDACTED]  
**Sent:** Friday, December 16, 2016 7:53 PM  
**To:** jeevacation@gmail.com  
**Cc:** Larry Visoski; Rich Kahn  
**Subject:** TWA: Hanger -completed  
**Attachments:** IMG\_9188.JPG; Untitled attachment 00076.txt; IMG\_9189.JPG; Untitled attachment 00079.txt; IMG\_9190.JPG; Untitled attachment 00082.txt; IMG\_9191.JPG; Untitled attachment 00085.txt; IMG\_9192.JPG; Untitled attachment 00088.txt; IMG\_9193.JPG; Untitled attachment 00091.txt; IMG\_9194.JPG; Untitled attachment 00094.txt; IMG\_9195.JPG; Untitled attachment 00097.txt

Hanger roof repaired from the inside until approved to work on the outside. S=Ivester said he would need to do TWA Roof just like he did the Tunnel Roof =