

---

**From:** Eric Roth <[REDACTED]>  
**Sent:** Monday, December 16, 2013 7:58 PM  
**To:** 'Jeffrey Epstein'  
**Cc:** 'Larry Visoski'  
**Subject:** FW: GIV 1085 - Bose system for discussion purpose only  
**Attachments:** image001.jpg; image002.jpg; image003.jpg; image010.jpg; image011.jpg; image012.jpg; Bose System Layout 121613.pdf

Je=frey,

It=appears that the subs will fit within the credenza, but you will lose =ll of the room in the fwd and aft areas to =ccommodate.

Pl=ase take a moment to review the attached dwg. "Exact" =ositioning has not been established and must take into account existing =ootprints, etc... At this point, this is for conceptual =urposes.

Do=s everything look ok to you?

=nbsp;| PRESIDENT

P [REDACTED] | C =16.857.6533 | [REDACTED] | www.intljet.com

----- =----- =----- =----- =----- =----- =----- =o:p>

2221 Smithtown Avenue, Long =lant MacArthur Airport, Ronkonkoma, New York =1779

From:=/b> =eric Roth [mailto:[REDACTED]]  
Sent: Monday, December =6, 2013 2:20 PM

To: 'Dan Garofalo'  
Cc: [REDACTED]  
Subject: GIV 1085 - Bose system for discussion purpose only

</=:p>

</=:p>

</=:p>

</=:p>

</=:p>

</=:p>

=nbsp;| PRESIDENT

P [REDACTED] | C =16.857.6533 | [REDACTED] | www.intljet.com

----- = ----- = ----- = o:p>

2221 Smithtown Avenue, Long Island MacArthur Airport, Ronkonkoma, New York =1779

=