

---

**From:** Emad Hanna <[REDACTED]>  
**Sent:** Tuesday, December 14, 2010 10:28 PM  
**To:** Jeffrey Epstein  
**Subject:** Pictures  
**Attachments:** 12-14-10 Laundry Room Dryer Vent.jpg; 12-14-10 Laundry Room Dryer Vent1.jpg;  
12-14-10 Master Bedroom Primer1.jpg; 12-14-10 Master Bedroom Primer2.jpg;  
12-14-10 Master Bedroom Primer3.jpg; 12-14-10 Master Bedroom Primer4.jpg;  
12-14-10 Master Bedroom Road Fish Tails.jpg; 12-14-10 Master Bedroom Road Fish  
Tails2.jpg; 12-14-10 Master Bedrrom Road Coconut.jpg

Jeffrey,

The laundry room dryer vent in the 1st =wo pictures show the cutting of the electrical conduit for the AC which =’m told if someone had looked out side on the roof this would have been =oticed and maybe avoided?

Igala was missing 6 of his crew members today due =o vacation and one working the barge and another helping =rian.

Thank you

<=p>

Emad Hanna

Project Controller

HBRK Associates

301 East 66th St

Suite 10F

New York, NY 10065

Cell [REDACTED]

LSJ Office [REDACTED]

St. Thomas Office [REDACTED]

NY Office [REDACTED]

Fax [REDACTED]

[REDACTED]