

---

**From:** Richard Kahn <[REDACTED]>  
**Sent:** Tuesday, September 25, 2012 2:34 PM  
**To:** Jeffrey Epstein  
**Subject:** Buck Steel  
**Attachments:** SKMBT\_C25312092510080.pdf; Untitled attachment 00019.htm

after speaking with Buck Steel yesterday and as you suspected the middle section of the 60' side cannot have doors as they have hurricane tracings is diagram below with red markings ok to proceed with please advise

Richard Kahn  
HBRK Associates Inc.  
575 Lexington Avenue, 4th Floor,  
New York, New York 10022  
tel: [REDACTED]  
fax: [REDACTED]  
cell: [REDACTED]

Begin forwarded message:

**From:** [REDACTED]  
**Date:** September 25, 2012 10:09:04 AM EDT  
**To:** [REDACTED]  
**Subject:** Message from KMBT\_C253  
**Reply-To:** [REDACTED]

=