
From: Larry Visoski [REDACTED]
Sent: Monday, May 2, 2016 6:50 PM
To: [REDACTED]
Subject: Je vacation
Attachments: Fwd: Scan from Meridian Jet Center
img-502135453-0001.pdf; Untitled attachment 00072.htm

Jeffrey

Pete informs that zero or lower voltage may only be seen with Takeoff power, Since that is hottest ai= going thru Precooler,

=div id="AppleMailSignature">

Sent from my iPhone

Beg=n forwarded message:

From:</> Pete Rawson [REDACTED] >
Date: May 2, 2016 at 2:02:45 PM AST
To: [REDACTED]
Subject: FW: Scan f=om Meridian Jet Center

Hi Larry,
Here are th= readings that I got after the fan air valve swap.
These ar= before the filter unit changes.

We only w=nt to 90%, and didn't wait for a response.
I'm sure that th= readings would have changed if we waited.

Regards,=span>

Pete

-----Original Message-----

From: Meridian Jet Center [mailto:[REDACTED]]
Sent: Monday, May 02, 2016 1:55 PM
To: Pete Rawson <[REDACTED]>=span>
Subject: Scan from Meridian Jet Center

Please open the attached document. It was scanned and sen= to you from Meridian Jet Center.

Number o= Images: 2

Attachment File Type: PDF

Device Name: Meridian Jet Center

Device Location:=

For more information, please visit <http://www.meridian.aero/>

=