

Year	1997
Manufacturer	GULFSTREAM
Model	V
For Sale	Call
Location	PHL
Condition	Used
Serial Number	507
Registration Number	N507DW
Total Time	5247
Number Of Seats	14pax 4crew

Airframe:

5247.2 Hours 2,382 Landings
 Date of Manufacture (CofA): June 30, 1997

APU: Honeywell RE220-GV S/N: P-10 5,194 Hours APU Enrolled on Honeywell MSP Gold

Engine Specs:

Rolls Royce BR700-710A1-10
 Engines are Enrolled on Rolls-Royce CorporateCare
 Left (Eng. #1): S/N: 11137 4,941.7 Hours 2,207 Cycles
 Right (Eng. #2): S/N: 11138 4,935.5 Hours 2,221 Cycles
 Left: Midlife c/w July 10, 2012 at 3,696.9 Eng. Hrs. and 1,774 Cycles
 Right: Midlife c/w July 10, 2012 at 3,690.7 Eng. Hrs. and 1,778 Cycles

Avionics/Radios:

Honeywell SPZ-8500 Dual Autopilot/Flight Director System
 Dual Collins VHF-422D Comms w/ 8.33 Spacing
 Dual Collins VIR-432 NAV Receivers w/ FM Immunity
 Dual Collins ADF-482 ADF
 Dual Collins DME-442 DME
 Triple Honeywell AZ-840 Micro Air Data Computers
 Dual Collins TDR-94D Mode S Transponders w/ Enhanced Flight ID & ADS-B Out
 Dual Collins HF-9034A HF Comm
 Dual Honeywell RT-300 Radio Altimeters
 Triple Honeywell Laserref IV HG-2001 Laser Reference Units (IRS)
 Triple Honeywell NZ-2000 FMS w/ 5.2 Software
 Honeywell Primus WU-880 Color Weather Radar
 Honeywell DL-950 Data Loader
 Honeywell TCAS-CAS-67A
 Honeywell Mark V EGPWS Computer
 Flight Data Recorder (FDR)
 Voice Recorder (CVR)
 Artx 406-2 Emergency Locator Transmitter (ELT)

Additional Equipment:

Dual Life Rafts with Artx 406 ELT's
 Electronic Flight Bags
 ASC-192A ADS-B Out c/w August, 2013

Exterior:

New Paint September 2013 @ Duncan Aviation – Battle Creek, MI
 White with blue and gray stripe

Interior: August 2013

New cockpit seats, glare shield, control column boots, new carpet cockpit through baggage, new Dynamo cold storage unit in aft galley and all new cabin LED lighting in August 2013 @ Gulfstream – Westfield, MA.

The fourteen (14) passenger interior and 4 crew with crew jump seat features a forward crew rest area, forward crew galley annex PPI coffee pot, ice drawer, and drink storage, forward crew lavatory, and an aft main galley and aft main lavatory. The fireblocked interior features a forward-cabin 4-place club, a mid-cabin left-side 4-place conference group opposite a credenza, and an aft-cabin 4-place berthing divan on left side and two single seats on the right. The forward and aft seating arrangements include pull-out executive tables between the opposing chairs. The club and conference group chairs are upholstered in light beige leather.

Cabin entertainment includes Genesis Airshow, one multi-disc DVD's and one blue ray, one fwd bulkhead monitor and one mid-cabin HD monitor. The aft full-service galley features microwave and cold storage unit, dual Krups coffee makers, galley sink with cold/hot potable water, dual ice drawers, and ample storage drawers.

Inspection Status:

Engines enrolled on Rolls-Royce CorporateCare.
 APU enrolled on Honeywell MSP Gold
 Avionics enrolled on Honeywell Avionics Protection Plan (HAPP) and Collins (CASP).
 Aircraft enrolled on Honeywell Mechanical Protection Program (MPP).
 Aircraft enrolled on CMP Maintenance Tracking Programs.
 Heavy maintenance performed primarily at Gulfstream.
 Maintenance records are intact and complete.
 48,72, 96 and 192 Month inspection c/w August 2013.
 All CB's current to date