

---

**From:** [REDACTED]  
**Sent:** Tuesday, July 19, 2011 7:36 PM  
**To:** anthony valenti  
**Attachments:** IMG\_6005.jpeg; IMG\_6006.jpeg; IMG\_6007.jpeg; IMG\_6008.jpeg; IMG\_6009.jpeg; IMG\_6010.jpeg

Hi Anthony,

I just returned to NY and the floors look great! The only thing that I have an issue with is the baseboards in the linen closet. Please see the attached photos.. There are huge gaps between the walls and the baseboards and it just looks really bad. I'm sure it's because the walls aren't even, but perhaps just a small moulding should have been used instead in the closet instead. On the longest wall in the closet, they used 2 pieces of baseboard instead of just one continuous. Also, there is a huge gap on the floor molding under the door(not sure what you call it, but it's in the last photo) What do you think?