
From: Ann Rodriguez <[REDACTED]>
Sent: Wednesday, April 26, 2017 2:54 PM
To: Jeffrey
Subject: Master Bath shower & Door
Attachments: image1.JPG; Untitled attachment 00424.txt; image2.JPG; Untitled attachment 00427.txt; image3.JPG; Untitled attachment 00430.txt; image4.JPG; Untitled attachment 00433.txt; image5.JPG; Untitled attachment 00436.txt

Hey Bossman,

Danny E. decided to do a blow out from the valve to see if that could be the=problem and it worked. The stuff that came out feels like shard glass and h=s been clogging everything

Restroom door is open.

Danny V. is on GSJ fixing the water maker so Danny E. is working on your sho=er in the master