
From: Larry Visoski <████████>
Sent: Sunday, January 28, 2018 12:55 AM
To: Je vacation
Cc: Rich Kahn
Subject: GIV

Jeffrey

Pete and I swapped the #5 Display tube with #2 tube.,.

The issue is confirmed we have a bed display tube, the problem followed the t=be,, this is covered under our HAPP program This week,. Pete would like to complete routine 150 Engine inspection, which=entitles „engine oil filter and fuel filter inspection while we are in tet=rboro.,

Is this approved?

Thx
Larry

Sent from my iPhone=<?xml version=.0" encoding=TF-8"?> <!DOCTYPE plist PUBLIC "-//Apple//DTD PLIST 1.0//EN" "http://www.apple.com/DTDs/PropertyList-1.0.dtd">
<plist version=.0">
<dict>
 <key>conversation-id</key>
 <integer>17392</integer>
 <key>date-last-viewed</key>
 <integer>0</integer>
 <key>date-received</key>
 <integer>1517100872</integer>
 <key>flags</key>
 <integer>8590195717</integer>
 <key>gmail-label-ids</key>
 <array>
 <integer>2</integer>
 </array>
 <key>remote-id</key>
 <string>790734</string>
</dict>
</plist>