

---

**From:** Jeffrey Epstein <jeevacation@gmail.com>  
**Sent:** Thursday, January 31, 2013 10:59 AM  
**To:** [REDACTED]  
**Subject:** Re: GIV prebuy list

good work,

On Thu, Jan 31, 2013 at 2:22 A=, [REDACTED] wrote:

Jeffrey

here is the prebuy list I have compiled, it is adjusted Gulfstream Sur=ey that excludes the 38 items completed during the 72 month inspection, =20 I personally included the items due in Sept 2013 which include below floo= inspection, FS85 which is the Popping inspection, and flap inspection. (items 99 - 113)

I will have Gulfstream in PBI provide an estimate for this labor?  
do you approve of my list?

thank you,  
Larry

Schedule " E"

Prebuy Serial # 1085 N423TT

GIV Modified Factory Gulfstream Aircraft Records and Condition Survey

1. =A0 Perform Aircraft/Rec=rds and condition Survey
2. =A0 CMP code: 100310 Che=k Airworthiness and Directives
3. =A0 100320 check service=bulletins
4. =A0 134401 c/w avionics=20 inventory
5. =A0 191108 review aircra=t status and records
6. =A0 231001 Avionics Func=ional ramp test
7. =A0 291030 Combined Hydr=ulic System DPI (engine driven pump by-pass) inspection.
8. =A0 291031 Flight Hyd sy=tem inspection (engine driven Pump by-pass).
9. =A0 291032 Combined Hyd =ystem DPI inspection (main pressure)

10. =A0 291033 flight Hy= dpi inspection (main pressure)
11. =A0 291034 Combined =yd inspection (main return)
12. =A0 291035 flight Hy= inspection (main return).
13. =A0 292020 Auxiliary=system DPI (pressure) inspection .
14. =A0 292021 Aux syste= DPI (return). Inspection.
15. =A0 292024 Utility S=stem DPI (pressure) inspection.
16. =A0 292025 Uti=ity System DPI (Pump by-pass) inspection.
17. =A0 324108 wheel bra=e lining check
18. =A0 551019 Horizonta= Stabilizer / Elevator exterior inspection L/H
19. =A0 551020 Horizonta= Stab exterior R/H inspection
20. =A0 553005 Vertical =tab / Rudder exterior inspection
21. =A0 554007 Rudder ex=ernal inspection
22. =A0 571005 Wing exte=ior L/H inspection
23. =A0 571006 Wing exte=ior R/H inspection
24. =A0 490002 Auxiliary=Power unit Ops test
25. =A0 490005 APU enclo=ure inspection
26. =A0 490052 APU – O=eration Test
27. =A0 710025 Engine Bo=escope inspection
28. =A0 710031 Engine Op=ration test
29. =A0 732001 Engine Ac=eleration Test / Adjustment (related code).
30. =A0 732005 Engine de=eleration test
31. =A0 732049 engine ha=dling ACU solenoid ops check.
32. =A0 732057 engine ap=roach idle solenoid ops check.
33. =A0 732011 Ground id=e, engine –test / Adjustment
34. =A0 732013 approach =dle- adjustment / test
35. =A0 783013 Thrust Re=erser (TR) interlock feedback system LH ops test

36. =A0 783014 Thrust Re=erser interlock feedback ops
37. =A0 <=span>783017 Max Reverse Thrust ops test L/H
38. =A0 783018 Max Rever=e R/H ops test
39. =A0 742006 Number 2 =ngine igniter plug, inspection, lower
40. =A0 742016 Number 2 =ngine inginter plug inspection, upper
41. =A0 774955 Engine ch=p detector visual
42. =A0 792007 filter en=ine oil pressure,.
43. =A0 791033 engine oi= level
44. =A0 792013 engine sc=venge strainers
45. =A0 710026 Engine Bo=escope
46. =A0 710032 engine op= test
47. =A0 732002 engine ac=eleration test
48. =A0 732006 engine de=eleration test
49. =A0 732050 Engine ha=dling ACU solenoid
50. =A0 732058 Engine ap=roach Idle Solenoid ops test
51. =A0 750006 Airflow c=ntrol system test
52. =A0 732012 Ground id=e Engine test
53. =A0 732014 approach =dle adjustment test
54. =A0 742008 #2 ignite= plug inspection lower
55. =A0 742018 #2 ignite= plug inspection upper
56. =A0 774956 Engine ch=p detector visual
57. =A0 792014 Engine sc=venge strainers inspection
58. =A0 320011 Nose land=ng gear and components detailed inspection.
59. =A0 320006 nose land=ng gear lube
60. =A0 320028 Nose gear=shock strut assy corrosion inhibit compound apply
61. =A0 320030 Nose gear=truss brace assy corrosion inhibit apply

- 62. =A0 32001 Nose gear =pper Tunn attach points
- 63. =A0 320032 Nose gear=drag brace
- 64. =A0 320033 Nose stri=er arm
- 65. =A0 322036 nose gear=axle fitting
- 66. =A0 325001 Nose whee= steering functional test
- 67. =A0 325010 nose whee= steering R/R
- 68. =A0 320013 Main land=ng gear and components detailed inspection
- 69. =A0 320004 MLG (main=landing gear) lube
- 70. =A0 320015 MLG axle =itting attach pin
- 71. =A0 320017 MLG Axle =itting L/H
- 72. =A0 320019 Shock abs=rber
- 73. =A0 320021 MLG side =race
- 74. =A0 320023 MLG uploc= roller
- 75. =A0 320025 MLG strik=r arm
- 76. =A0 321015 MLG spind=e pin
- 77. =A0 321031 MLG shock=Absorber L/H
- 78. =A0 321075 main land=ng gear trunnion Pin
- 79. =A0 323002 landing g=ar cycle
- 80. =A0 324250 MLG wheel=assy
- 81. =A0 324108 brake lin=ng check, please comply with all brakes
- 82. =A0 320014 MLG and c=mponents detailed inspection
- 83. =A0 320005 MLG lube<=font>
- 84. =A0 320016 MLG axle =ttach pin fitting L/H
- 85. =A0 320018 MLG axle =itting R/H
- 86. =A0 320020 MLG shock=absorber
- 87. =A0 320022 MLG side =race

88. =A0 320024 uplock ro=ler

89. =A0 320026 MLG strik=r arm

90. =A0 321016 MLG spind=e pin

91. =A0 321032 MLG spind=e absorber

92. =A0 321076 MLG trunn=on

93. =A0 275010 flap actu=tor inspection

94. =A0 275011 flap act<=font>

95. =A0 275012 flap outb=ard inspt

96. =A0 275027 flap bush=ng inspection

97. =A0 275028 flap bush=ng

98. =A0 280005 fuel cont=ol system functional test

99. =A0 303005 pitot hea= ops

100. =A0            531007 FS 85 Bulkhea= inspection

101. =A0            532007 Forward cabin=compartment below floor inspection

102. =A0            532009 midcabin belo= floor inspection

103. =A0            551019 horizontal st=b / elevator exterior inspection L/H

104. =A0            551020 horizontal st=b / elevator exterior inspect R/H

105. =A0            551023 horizontal st=b inspection internal

106. =A0            551024 horizontal st=b inspec

107. =A0            553005 vertical stab=/ Rudder external inspection

108. =A0            553007 vertical stab=/ rudder inspect

109. =A0            571011 Wing front be=m hi-lite collars left

110. =A0            571012 wing front be=m hi-lite collars right

111. =A0            571025 wing tank int=rrior inspection

112. =A0            571026 wing tank rig=t inspection

113. =A0            Gulfstream flight te=t with Gulfstream test pilot

<=r clear="all">

--

\*\*\*\*\*=\*\*\*\*\*

The information contained in this communication is confi=ential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the a=dressee. It is the property of Jeffrey Epstein Unauthorized use, di=closure or copying of this communication or any part thereof is strictl= prohibited and may be unlawful. If you have received this communication in error, p=ease notify us immediately by return e-mail or by e-mail to jeevacation@gmail.com, =nd destroy this communication and all copies thereof, including all attachm=nts. copyright -all rights reserved