
From: brice gordon <[REDACTED]>
Sent: Tuesday, August 7, 2018 2:45 PM
To: jeevacation@gmail.com
Cc: [REDACTED]
Subject: LSJ Master Shower
Attachments: IMG_2364.jpg; Untitled attachment 00255.txt

Good morning

Attached photo of shower thermostatic valve for master shower To replace valve completely will require removing tile from around the shower body I believe I can apply a fix that will last until we swap out for new fixture= Working on booster pump and drain issue Regards Brice