
From: brice gordon [REDACTED]
Sent: Wednesday, October 3, 2018 11:08 AM
To: J
Subject: Re:

Morning

They need to complete their work which involves the final treatment to protect / seal the surface from bleaching.

The proposed 30 days will be needed to brush out any imperfection in the diamond plate left after acid washing. My recommendation is they need to complete periodically during this time to check/ monitor chemical etc, we should not be responsible.

I will address this issue this morning

<div id="AppleMailSignature">Sent from my iPhone

On Oct 2, 2018, at 4:31 PM, J <jeevacation@gmail.com <mailto:jeevacation@gmail.com>> wrote:

what is wrong with the flagpole pool finish , his 30 day story is not real we have never done that before

--

 please note

The information contained in this communication is confidential, may be attorney-client privileged, may constitute inside information, and is intended only for the use of the addressee. It is the property of

JEE

Unauthorized use, disclosure or copying of this communication or any part thereof is strictly prohibited and may be unlawful. If you have received this communication in error, please notify us immediately by return e-mail or by e-mail to jeevacation@gmail.com <mailto:jeevacation@gmail.com>, and destroy this communication and all copies thereof, including all attachments. Copyright -all rights reserved

=