
From: Larry Visoski [REDACTED]
Sent: Wednesday, May 17, 2017 1:55 AM
To: Je vacation
Cc: Rich Kahn
Subject: Cabin windows in Nautica
Attachments: 10A9B4EA-C210-47F2-AF1C-1635908491FC.JPG; Untitled attachment 00383.txt; 62CDAB99-A451-407E-9634-F416B3BC2511.JPG; Untitled attachment 00386.txt; 944320FF-D3E9-4456-B0CA-76CB357CD668.JPG; Untitled attachment 00389.txt; F5B78188-0F64-468A-9658-73177EA031EE.JPG; Untitled attachment 00392.txt; 7EAD9C1E-4E90-4968-9C0F-978F742B64C8.JPG; Untitled attachment 00395.txt; 85E632EC-5A5C-4CCE-A932-D2C7D0793E4F.JPG; Untitled attachment 00398.txt

Jeffrey

Once the shop removed the wood trim that held the Vinyl interior trim, it left some rough edges around the window trim area.

If you look close around the window edges on photos 2 and subsequent,. Edges=are irregular.

The interior shop is trying to come up with a solution,.to make it look clean and finished.

1-Simple Bondo and paint?

2-White Window sealant / caulking?

3-fabricate fiberglass interior trim?

Do you have any ideas you prefer?

Thx, larry

Wood trim that was used to hold interior panels, that where removed.,